

Thermo-hygrometers



C.A 846

- > 2 in 1: hygrometry and ambient temperature measurement
- > Easy to use

C.A 1244

- > 3 in 1: hygrometry, ambient temperature and dew point measurement
- > Remote probe for greater accessibility
- > Particularly easy to read with its dual backlit display

C.A 847

- > Measure the humidity of your materials quickly and simply: prick the material and note the value corresponding to the LED lit

Specifications

	C.A 846	C.A 1244	C.A 847
RH range	0 to 100% RH	5 to 95% RH	6 to 100% RH
RH accuracy	±2.5% at 25 °C from 10% to 90% ±5% at 25 °C from 0% to 10% HR and from 90% to 100%	+1.8% RH	±1 LED
Temperature range	-20°C to +60 °C	-20°C to +70 °C	-
Temperature accuracy	±0.5 °C	±0.4% R +0.3 °C	-
Dew point	-	Yes	-
Functions	Max, Hold	Min, Avg	-
Dimensions / weight	173 x 60.5 x 38 mm / 185 g	147.7 x 70.6 x 34.7 mm / 190 g	173 x 60.5 x 38 mm / 160 g

State at delivery

- > The **C.A 846**, **C.A 1244** and **C.A 847** delivered with 1 battery and 1 user guide in 5 languages

Accessories/Replacement parts



> For C.A 846 and C.A 1244

- 33 % salt cartridge
- 75 % salt cartridge

- > P01156402
- > P01156401

> For C.A 1244

- Telescopic extension

- > P01102012

References to order

- > **C.A 846** > P01156301Z
- > **C.A 847** > P01156302Z
- > **C.A 1244** > P01156310